



SUPERIOR

WASHER & GASKET CORP.

Part Number	Material	OD	ID	Free HT	Size	Thickness	
675-10-002	=Phosphor-Bronze	.073	.035			.002	Flat Washer
675-11-012	=Phosphor-Bronze	.087	.062			.012	Flat Washer
675-12-005	=Phosphor-Bronze	.118	.062			.005	Flat Washer
675-13-010	=Phosphor-Bronze	.125	.062			.010	Flat Washer
675-14-005	=Phosphor-Bronze	.167	.062			.005	Flat Washer
675-15-031	=Phosphor-Bronze	.187	.062			.031	Flat Washer
675-16-008	=Phosphor-Bronze	.156	.068			.008	Flat Washer
675-17-031	=Phosphor-Bronze	.188	.068			.031	Flat Washer
675-18-010	=Phosphor-Bronze	.199	.068			.010	Flat Washer
675-19-005	=Phosphor-Bronze	.161	.081			.005	Flat Washer
675-20-031	=Phosphor-Bronze	.218	.094			.031	Flat Washer
675-21-005	=Phosphor-Bronze	.139	.095			.005	Flat Washer
675-22-032	=Phosphor-Bronze	.250	.095			.032	Flat Washer
675-23-010	=Phosphor-Bronze	.156	.098			.010	Flat Washer
675-24-016	=Phosphor-Bronze	.218	.098			.016	Flat Washer
675-25-010	=Phosphor-Bronze	.186	.103			.010	Flat Washer
675-26-031	=Phosphor-Bronze	.312	.109			.031	Flat Washer
675-27-016	=Phosphor-Bronze	.271	.119			.016	Flat Washer
675-28-005	=Phosphor-Bronze	.187	.125			.005	Flat Washer
675-29-020	=Phosphor-Bronze	.209	.125			.020	Flat Washer
675-30-031	=Phosphor-Bronze	.250	.125			.031	Flat Washer
675-31-010	=Phosphor-Bronze	.281	.125			.010	Flat Washer
675-32-031	=Phosphor-Bronze	.375	.125			.031	Flat Washer
675-33-018	=Phosphor-Bronze	.315	.133			.018	Flat Washer
675-34-005	=Phosphor-Bronze	.218	.140			.005	Flat Washer
675-35-031	=Phosphor-Bronze	.406	.140			.031	Flat Washer
675-36-032	=Phosphor-Bronze	.242	.152			.032	Flat Washer
675-37-006	=Phosphor-Bronze	.375	.156			.006	Flat Washer
675-38-031	=Phosphor-Bronze	.437	.156			.031	Flat Washer
675-39-031	=Phosphor-Bronze	.312	.161			.031	Flat Washer



SUPERIOR

WASHER & GASKET CORP.

Part Number	Material	OD	ID	Free HT	Size	Thickness	
675-40-005	=Phosphor-Bronze	.271	.167			.005	Flat Washer
675-41-015	=Phosphor-Bronze	.262	.187			.015	Flat Washer
675-42-031	=Phosphor-Bronze	.312	.187			.031	Flat Washer
675-43-062	=Phosphor-Bronze	.437	.187			.062	Flat Washer
675-44-040	=Phosphor-Bronze	.500	.187			.040	Flat Washer
675-45-003	=Phosphor-Bronze	.232	.191			.003	Flat Washer
675-46-025	=Phosphor-Bronze	.347	.191			.025	Flat Washer
675-47-063	=Phosphor-Bronze	.500	.191			.063	Flat Washer
675-48-010	=Phosphor-Bronze	.375	.195			.010	Flat Washer
675-49-062	=Phosphor-Bronze	.437	.195			.062	Flat Washer
675-50-010	=Phosphor-Bronze	.250	.197			.010	Flat Washer
675-51-012	=Phosphor-Bronze	.345	.198			.012	Flat Washer
675-52-025	=Phosphor-Bronze	.383	.198			.025	Flat Washer
675-53-003	=Phosphor-Bronze	.406	.203			.003	Flat Washer
675-54-014	=Phosphor-Bronze	.437	.203			.014	Flat Washer
675-55-040	=Phosphor-Bronze	.562	.203			.040	Flat Washer
675-56-005	=Phosphor-Bronze	.359	.212			.005	Flat Washer
675-57-040	=Phosphor-Bronze	.625	.234			.040	Flat Washer
675-58-005	=Phosphor-Bronze	.312	.252			.005	Flat Washer
675-59-003	=Phosphor-Bronze	.366	.252			.003	Flat Washer
675-60-010	=Phosphor-Bronze	.496	.252			.010	Flat Washer
675-61-005	=Phosphor-Bronze	.375	.255			.005	Flat Washer
675-62-062	=Phosphor-Bronze	.562	.255			.062	Flat Washer
675-63-005	=Phosphor-Bronze	.592	.255			.005	Flat Washer
675-64-062	=Phosphor-Bronze	.625	.255			.062	Flat Washer
675-65-062	=Phosphor-Bronze	.687	.255			.062	Flat Washer
675-66-031	=Phosphor-Bronze	.375	.265			.031	Flat Washer
675-67-010	=Phosphor-Bronze	.390	.265			.010	Flat Washer
675-68-062	=Phosphor-Bronze	.437	.265			.062	Flat Washer
675-69-062	=Phosphor-Bronze	1.000	.281			.062	Flat Washer



SUPERIOR

WASHER & GASKET CORP.

Part Number	Material	OD	ID	Free HT	Size	Thickness	
675-70-005	=Phosphor-Bronze	.468	.312			.005	Flat Washer
675-71-010	=Phosphor-Bronze	.500	.312			.010	Flat Washer
675-72-062	=Phosphor-Bronze	.750	.312			.062	Flat Washer
675-73-031	=Phosphor-Bronze	.487	.317			.031	Flat Washer
675-74-015	=Phosphor-Bronze	.461	.320			.015	Flat Washer
675-75-005	=Phosphor-Bronze	.500	.338			.005	Flat Washer
675-76-031	=Phosphor-Bronze	.687	.343			.031	Flat Washer
675-77-009	=Phosphor-Bronze	.461	.379			.009	Flat Washer
675-78-040	=Phosphor-Bronze	.750	.390			.040	Flat Washer
675-79-031	=Phosphor-Bronze	.812	.410			.031	Flat Washer
675-80-020	=Phosphor-Bronze	.694	.440			.020	Flat Washer
675-81-005	=Phosphor-Bronze	.750	.440			.005	Flat Washer
675-82-062	=Phosphor-Bronze	.875	.469			.062	Flat Washer
675-83-003	=Phosphor-Bronze	.750	.507			.003	Flat Washer
675-84-090	=Phosphor-Bronze	1.062	.531			.090	Flat Washer
675-85-125	=Phosphor-Bronze	1.125	.531			.125	Flat Washer
675-86-062	=Phosphor-Bronze	1.250	.531			.062	Flat Washer
675-87-031	=Phosphor-Bronze	.821	.593			.031	Flat Washer
675-88-125	=Phosphor-Bronze	1.234	.767			.125	Flat Washer
675-89-061	=Phosphor-Bronze	1.245	.784			.061	Flat Washer
675-90-031	=Phosphor-Bronze	1.125	.843			.031	Flat Washer
675-91-080	=Phosphor-Bronze	1.187	.875			.080	Flat Washer
675-92-062	=Phosphor-Bronze	1.625	1.043			.062	Flat Washer